

seasoned. We also have joists to supply the place of those which are found to be decayed when the old flooring is taken up.

New and strong corridor door with wire guards, to supply the place of the old ones which are considerably worn and are too weak.

One hundred wire-guards for windows.

Wood-work throughout the entire institution needs painting.

Twelve bath-rooms, separated from the water-closets, with three enameled face and hand sinks in each.

For the present the morning baths are had in basins in the dining rooms of the wards. This mode is inconvenient and is very objectionable for many reasons.

The water-closets should be overhauled, and new hoppers put in each one.

Twelve sinks, one in each ward for washing vessels.

Sewerage system should be overhauled and larger pipes put in.

Ventilation should be improved.

One dwelling for Steward.

One carpenter's shop. The old one is very much decayed.

Entirely new fences are needed around the court yards, and an improvement made on court yard grounds to avoid the present prison-like appearance.

New paling needed around the cemetery.

Plank fences around the farm need repairing.

Water works to be completed.

Four dumb-waiters, improved plan.

IMPROVEMENTS AND REPAIRS WANTED IN THE ENGINEER'S DEPARTMENT FOR 1883-'84.

One hand-power pipe cutting machine.

A new rotary washing machine to take the place of the one now in use.